

Terms and Conditions

Clause Number: Q617
Effective: 07/26/2018
Page 1 of 1

SUBMITTAL OF METALLIC RAW MATERIAL SAMPLES

Supplier shall rubber stamp raw material requiring a test sample with a verification mark across the cut-line prior to cutting the sample from the stock.

Approximately one half of the impression is to be on each side of the cut line.

The supplier code shall be stamped within the verification stamp.

The purchase order number, supplier code and heat lot number shall be applied to the raw stock and the sample of the stock from which it was cut.