

Q836 **Rework/Repair Report - rev 3/6/01**

Upon receipt of material returned due to a nonconforming condition, the Seller shall validate the reason for the return, whether or not it was determined to be the Seller's responsibility. The Seller may, at his option, rework, replace or partially replace the material, as required, to return it to a conforming condition. After rework/repair action has been taken, the Seller shall include a Rework/Repair Report with each invoiced material shipment to The Boeing Company. The report shall summarize the Seller's evaluation of the nonconformance, outline the rework/repair action taken, list the subsequent acceptance tests performed, and document the acceptance test results. In the event the nonconformance cannot be substantiated, the action taken is: "No Work Done."